25X1

IDEA 0003-69 Copy 4 of 5

6 January 1969

MEMORANDUM FOR: Deputy for Operations, OSA

SUBJECT:

Quarterly Operational Report

REFERENCE:

Memorandum dated 12 April 1968, Subject: Monthly and Quarterly

Program Progress Reports

25X1A

Attached is the Quarterly Operational Summary and Status Report for the period 1 October 1968 to

25X1A

31 December 1968.

Lt. Colonel, USAF Chief, IDEALIST Division, OSA

Attachment - 1 As Stated

IDEA/OSA

(6 Jan 69)

Distribution:

#1 - D/O/OSA

#2 - IDEA/OSA

#3 - SAS/OSA

#4 - RB/OSA

#5

25X1A

25X1A

Approved For Release 2002/06/18 DP68B00724R000200270001-0

25X1

Attachment IDEA 0003-69

OPERATIONAL SUMMARY AND STATUS (1 October - 31 December 1968)

- I. Operational Mission Summary:
- a. On 1 October 1968, the stand-down on operational missions, imposed by the U.S. was lifted to the extent that approval was granted to conduct ELINT and photo reconnaissance missions peripherally a minimum of 20 nautical miles offshore.
- b. Six Agency U-2 missions were flown during the second quarter of FY 69. Nine other missions were alerted, however, four were cancelled due to weather, four for lack

however, four were cancelled due to weather, four for lack

25X1

25X1

Attachment IDEA 0003-69 Page 2

first operational mission. This mission was designed to obtain "H" Camera photo coverage from approximately 60 NM east of Hong Kong along the coast of China to a point southeast of Shanghai. Pilot reported contrails in the vicinity of Lung-Tien and Nan Jin-Tao Airfields. Over all photo analysis was considered good with 20% cloud cover.

25X1C

3. Mission C178C was a round robin mission

25X1C

This

was an "H" Camera mission planned off the east coast of Hainan Island and then northeast, parallel to the China Coast, to a point off Swatow. Over all photo quality was fair with 10% cloud cover. Pilot reported no unusual sightings.

4. Mission Cl98C was flown on 7 November
This

25X1C

"H" Camera mission was programmed to obtain photographs of coastal targets from the Port Arthur area, along the Shantung Peninsula, south along the China mainland to a point northeast of Matsu Island. Pilot reported two

Approved For Release 2002/06/18: CIA-RDP68B00724R000200270001-0

25X1

Attachment IDEA 0003-69 Page 3

| heavy contrails in the vicinity of Lu Chiao Airfield, | 25X1C |
|---|--------------------|
| however, no known intercepts were attempted. Pilot and | 23/10 |
| | |
| | |
| | : |
| | : |
| activity. Photo quality was fair with 20% cloud cover. | <u> </u> |
| 5. Mission C228C was flown on 14 November from | ! |
| | 25X1C |
| This | 23/10 |
| mission was designed to collect ELINT along the south- | |
| east coast of China from the northeast tip of Hainan | |
| Island to a point 35 NM northeast of Hai Tan Island. | 25X1C |
| Pilot reported no unusual activity. | 25X1C |
| | : : |
| · | |
| . · · · · · · · · · · · · · · · · · · · | 25X1C |
| 6. Mission C278C was a round robin mission flown | ₁ 25X1C |
| on 19 December 1968. | 25/10 |
| | 1 |
| mission. The route was planned to obtain photographic | - |
| coverage of coastal targets from the Shanghai area, south | |

25X1C

Approved For Release 2002/06/13 : CIA RDP68B00724R000200270001-0

| and the second second | | and the second s | | |
|--|------------------|--|---------------|-------------|
| A 10 10 10 10 10 10 10 10 10 10 10 10 10 | or Release 2002/ | ACIAS - CIA DDI | DC0DAA794DAAA | 200227004 0 |
| Approved F | or Release Zuuzi | UD/13 : GIA-RIJI | 2006UU124KUUU | ZUUZ/UUU1-U |
| , .pp. 0 . 0 | | · · · · · · · · · · · · · · · · · · · | | |

25X1

25X1C

25X1C

25X1

25X1

Attachment IDEA 0003-69 Page 4

| along the China mainland | |
|--------------------------|--|
| | |
| | |
| | |
| | |
| | |

signals. No unusual sightings were reported by the pilot.

II. General:

a. SCOPE SAINT:

concerned.

Detachment "G" deployed Article 348 (U-2G) to

on 9 October 1968.

This operation was designed to exercise the Detachment

"G" deployment capability

A typical training

mission profile was flown from

and redeployment accomplished 16 October. A total of

30.0 hours was flown on the exercise and it

was considered highly successful by all parties

25X1C

TOP SECRET Approved For Release 2002/06/13 : CIA-RDP68B00724R000200270001Approved For Release 2002/06/13: CIA-RDP68B00724R000200270001-0 TOP SECRET 25X1 Attachment IDEA 0003-69 25X1D Page 5 RED DOT: Six RED DOT missions were accomplished using various cameras and film combinations in the U-2Rs and U-2Gs. ADF Checks: Four low flights to check interface compatability between the ADF and other systems were completed. Special Flights: Three high altitude photographic missions were

25X1

25X1D

interface tests were flown during this period.

flown in conjunction with

Miscellaneous Tests:

25X1

Attachment IDEA 0003-69 Page 6

25X1

| k. U-2R: | | , |
|----------|--|---|

053 - Returned to LAC for MOD program 3 October 1968.

Returned to and accepted on 6 December.

25X1A

052 - Returned to LAC for MOD program 23 October.

056 - Transferred to SAC on 3 October.

060 - Accepted on 18 October, transferred to SAC 30 October.

055 - Accepted on 28 October.

25X1A

25X1A

25X1

Attachment IDEA 0003-69 Page 7

| 1 mg 0 | |
|--|---------------------------------------|
| 061 - Accepted 8 November, transferred to SAC | on |
| 22 November. | |
| 054 - Accepted on 22 November. Returned to LA | .C |
| for on 12 December. | 25X1A |
| 1. Aircraft Incidents: | · · · · · · · · · · · · · · · · · · · |
| (1) On 13 November 1968, aircraft 057 piloted | l by |
| ground looped. During landing | 1eft |
| wing tip contacted runway and began a left skid. | Air- |
| craft departed the runway and came to a stop appro | ximately |
| 100 feet from the runway in soft sand. Aircraft | |
| apparently came through the landing without damage | and |
| was placed in PE on 14 November. Returned to OR s | status |
| 5 December 1968. Incident investigation was condu | ıcted |
| and report received this Headquarters | on |
| 1 December 1968. | |
| (2) On 18 December 1968, the canopy on aircra | ıft |
| 053 became unlatched between 12,000 and 15,000 fee | et. |
| Visual check of the aircraft revealed canopy was | still |
| attached to the aircraft. landing was | 25X1A |

accomplished with aircraft performing a slow ground

Approved For Release 2002/06/13

25X1

Attachment IDEA 0003-69 Page 8

| loop after left wing | | Subsequent | 25X1A |
|-----------------------|--------------------------|---------------|--------|
| investigation reveale | ed a faulty fuel transfe | r valve that | |
| was continuously tran | nsferring fuel without b | eing engaged. | |
| | ed procedures to prevent | | 25X1C |
| becoming disengaged i | | | 20/(10 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | 1 |

25X1A